



## Flint Hills Resources, LP Work Order Details

Org: FHR-PE  
Site: PE

WO #: PE68244

WO Desc: repair leaking flange on monomer line at PSV by monomer meters

Parent WO#:

WO Long Desc: AVO leak detected at flange.

WO Priority: 1

Location: 28353

O- FHR EPS-PERU

Asset:

Asset Service:

Entry Date: 4/18/2016

WO Status: CLOSE

Action Code: LDAR

Project #:

Originator: TRACY ADAMS

Status Date: 10/16/2016

Work Type: CM

Failure Class:

Job Plan:

Planned Start:

Actual Start: 4/18/2016

Review Date:

PM/Bundle:

Planned Completion:

Actual Completion: 4/18/2016

### Plant Information

RC: PERC01

Planner: WILLIAM STONEKING

MOC#:

When Code: RT

Lead Craft: MECH

MOC Status:

P&ID:

MOC Desc:

SIR/EIS Required:

### LDAR

Tag #:

1st Attempt Made:

LDAR Planning Notes:

Leak Type:

1st Attempt Was:

LDAR Additional Notes:

Size:

1st Attempt Due By: 4/23/2016

Leak Location:

After 1st Attempt PPM:

Location Orientation:

Final Due By: 5/3/2016

### Work Order Notes

RICH WILLIAMS

04/18/2016

replaced gasket and tightened

Completed by Emp #: \_\_\_\_\_

Signature: \_\_\_\_\_